

Addendum

This addendum contains information for the *HP 82182A Time Module Owner's Manual*, part number 82182-90001, dated January 1982.

Page 43, under The Alarm Catalog. When printing the alarm catalog, port 3 of the calculator should be empty or contain one of the following accessories only: the HP 82143A Printer, the HP 82160A HP-IL Module, or the time module. Improper operation may occur if another module or accessory is plugged into this port while the Alarm Catalog is being printed.



Corvallis Division

1000 N.E. Circle Blvd., Corvallis, OR 97330, U.S.A.