


HEWLETT  PACKARD

**Reserve
Power Pack**



Using your Reserve Power Pack

Align the contact strips on the battery pack with those in the Reserve Power Pack. Place the battery pack in the well provided and close the lid. Plug the calculator's ac adapter/re-charger into the bottom of the Reserve Power Pack and plug the other end of the recharger into an ac outlet.

The red light (a solid-state lamp) on the Reserve Power Pack will glow when the proper connections have been made and the battery pack is being charged. The light *does not* turn off when the charge is complete.

Your Reserve Power Pack was shipped from the factory with a fully charged battery pack. However, the battery pack may have discharged, so be sure to charge the battery pack fully before using it in your calculator. Normal charging time for a completely discharged battery pack to be fully charged in the Reserve Power Pack is about 6 hours.

Note: If the battery pack will not hold a charge, either it or the Reserve Power Pack may be defective. If the one-year warranty is in effect, return the complete Reserve Power Pack with battery pack to Hewlett-Packard according to the shipping instructions in your calculator's owner's handbook. If the warranty has expired, see your nearest dealer or use the Accessory Order Form to purchase a replacement item.